



## EPIC BALUAN



Supplier ID	Supplier Code	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0121	Friction Element - 24V40W T25x65 BA15d	851-22-0121	SD_CHIEFMA R_2022	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0121	Flat Belt - 250V 3A ,082315016	851-22-0121	SD_CHIEFMA R_2022	NO
404	VIHMS000020	CHONG LEE LEONG SENG CO LTD	851-22-0134	Mechanical Seal - V-Belt	MD_TAI-K_MECSEA_EA560-20C_20230105	SD_TAI-K_20220810-1	NO
404	VIHMS000020	CHONG LEE LEONG SENG CO LTD	851-22-0134	Mechanical Seal - flow control valve	MD_TAI-K_MECSEA_EA560-20C_20230105	SD_TAI-K_20220810-1	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Seal Ring - JISB2401 G280 HS70	MD_OC 112225	SDoc_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Parallel Pin - ARPSG8-2G3 G155 HS70	MD_OC 112225	SDoc_OC 112225	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Rectangular Ring - JIS B 2401 G105 HS70	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	O-Ring - JISB2401 G85 HS90	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Rectangular Ring - JIS B 2401 P32 HS90	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Valve Plug - ARPSG8-262 HS90	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Rectangular Ring - 95x120x15 20381-09905	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Rectangular Ring - JISB2401 G280 HS70	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	O-Ring - ARPSG8-2G3 G155 HS70	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	O-Ring - JIS B 2401 G105 HS70	MD_OC 112225	SDoC_OC 112225	NO
406	858174	COMTECH OIL SEPARATOR AND	851-22-0085	Wing Insert - JISB2401 G85 HS90	MD_OC 112225	SDoC_OC 112225	NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Thermometer - SUP6			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Guide - SS400			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Cover. Side. Safety Valve - CAC402			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Holder Assembly - NULL			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	T. Valve Yoke Assembly - CAC402			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Cover - 25KL3-P25-X (With GT-3V, Nipple)			NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Rotary Valve - MG5436 (X-Band, 25kW)			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Coupling - MG5223F (S-Band, 30 kW)			NO
409	VIHMS000218	DAIKAI ENGINEERING PTE LTD	851-22-28	Seat - 40W			NO
412	VIHMS000205	DELTA CO. LTD.	851-22-0110	Deflector - NULL	DL2211430	TR-209-05564	NO
412	VIHMS000205	DELTA CO. LTD.	851-22-0110	O-Ring - NULL	DL2211430	TR-209-05564	NO
412	VIHMS000205	DELTA CO. LTD.	851-22-0110	Backup Ring - NULL	DL2211430	TR-209-05564	NO
412	VIHMS000205	DELTA CO. LTD.	851-22-0110	Gasket - NULL	DL2211430	TR-209-05564	NO
412	VIHMS000205	DELTA CO. LTD.	851-22-0110	Gasket - For Lamp	DL2211430	TR-209-05564	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Bearing Metal - A10-PT1/4	MD-30545	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Coupling Ring - The following component is a recommended spare associated with WO INCINERATOR	MD-30546	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Coupling Bolt & Nut - NULL	MD-30547	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Mechanical Seal - NULL	MD-30548	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Oil Seal - The following component is critical spare as associated with life boat.	MD-30549	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Gasket - NULL	MD-30550	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Gasket - NULL	MD-30551	Multi-SDoC-851629	NO
427	VIHMS000043	FUJI TRADING CO., LTD.	851-22-62	Gasket - VPX-3405BUCL	MD-30552	Multi-SDoC-851629	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
429	537882	FURUNO SINGAPORE PTE. LTD.	851-22-0089	Spare Motor for X Band Radar scanner - NULL	MD_FEC_RA DAR_SN36AF - RSB099_2022 0301	SD_FEC_202 20301	Yes
429	537882	FURUNO SINGAPORE PTE. LTD.	851-22-0089	Spare Motor for S Band Radar scanner - NULL	MD_FEC_RA DAR_SN36AF - RSB099_2022 0301	SD_FEC_202 20301	Yes
429	537882	FURUNO SINGAPORE PTE. LTD.	851-22-0089/2	Magnetron for X- Band Radar - NULL	MD_FEC_RA DAR_SN36AF - RSB099_2022 0301	SD_FEC_202 20301	Yes
429	537882	FURUNO SINGAPORE PTE. LTD.	851-22-0089/2	Magnetron for S- Band Radar - NULL	MD_FEC_RA DAR_SN36AF - RSB099_2022 0301	SD_FEC_202 20301	Yes
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	O-Ring - G70-4d	9C9917(N128 60)	SD_ IMEX_202204 05	NO
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	O-Ring - P233-001-910-0	9C9917(N128 60)	SD_ IMEX_202204 05	NO
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	Sealing Ring - NULL	9C9917(N128 60)	SD_ IMEX_202204 05	NO
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	Spring - P522-402-0110-4	9C9917(N128 60)	SD_ IMEX_202204 05	NO
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	O-Ring - P559-401-01100-4	9C9917(N128 60)	SD_ IMEX_202204 05	NO
440	VIHMS000056	HITACHI ZOSEN CORPORATION	851-22-0106	O-Ring - G140-4d	9C9917(N128 60)	SD_ IMEX_202204 05	NO
451	657594	ISS MACHINERY SERVICES LIMITED	851-22-0071	O-Ring - Valve Assembly, Overflow	MD-31484	Multi-SDoC-984127	NO
451	657594	ISS MACHINERY SERVICES LIMITED	851-22-0071	Mechanical Seal - Valve Assembly, Injection	MD-31485	Multi-SDoC-984127	NO
451	657594	ISS MACHINERY SERVICES LIMITED	851-22-0071	O-Ring - NULL	MD-31486	Multi-SDoC-984127	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
468	VIHMS000084	MANENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Bursting Cap, Complete - S45C			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Bursting Disc - SUS410			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Cooling Jacket - SWPA			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Bursting Cap, Complete - SWPA			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Bursting Disc - SS400			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	851-22-0130	Cooling Jacket - SS400			NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - Dia.75x3/8	MD-33458	Multi-SDoC-576517	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - NBR	MD-33459	Multi-SDoC-576517	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - S45C	MD-33460	Multi-SDoC-576517	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - D-5	MD-33461	Multi-SDoC-124929	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - FC200	MD-33462	Multi-SDoC-994458	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Hydraulic Hose - SUJ2	MD-33463	Multi-SDoC-124929	NO
517	669798	TENTOSHI MARINE SERVICES CO., LTD.	851-22-14	Limit Switch - NBR	MD-33464	Multi-SDoC-124929	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
545	VIHMS000161	WRIST-KLEVENBERG SHIP SUPPLY NL B.V	851-22-40	Record Paper-NULL	ROT-000021811	ROT-000013070	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Mechanical Seal	851-22-0148	SD_CHIEFMAR_2023	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Wear Ring-A	851-22-0148	SD_CHIEFMAR_2023	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Wear Ring-B	851-22-0148	SD_CHIEFMAR_2023	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Gasket	851-22-0148	SD_CHIEFMAR_2023	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Ball Bearing	851-22-0148	SD_CHIEFMAR_2023	NO
403	VIHMS000019	CHIEFMAR S.R.L.	851-22-0148	Impeller (Dia.165)	851-22-0148	SD_CHIEFMAR_2023	NO

