



ALEXANDRA KOSAN



Supplier ID	Supplier Code	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
390	VIHMS000006	ALFA LAVAL NORDIC A/S	869-22-47	Mechanical Seal 35mm. For Ejector Pump - NULL	000001	000001	NO
390	VIHMS000006	ALFA LAVAL NORDIC A/S	869-22-47	Seal Ring For Ejector Pump - Standard No.02915070 1	000001	000001	NO
390	VIHMS000006	ALFA LAVAL NORDIC A/S	869-22-47	O-Ring For Ejector Pump - Standard No.02915070 1	000001	000001	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089/2	Shaft - NULL	MD-50195-41620	SDoC-50195-41620	NO
1769	448519	MARINE SUPPORT IKE	869-22-260	Coupling Pack Kit KN07	MD_869-22-260	SDoC_869-22-260	NO
459	VIHMS000075	KOREA MARINE SUPPLY CO., LTD	869-22-242	Motor Ball Bearing 6209-2Z/C3	MD-55578	Multi-SDoC-519363	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
524	VIHMS000140	TSS ROTTERDAM B.V.	869-22-230/2	Set OfGaskets	39294-2	39294	NO
524	VIHMS000140	TSS ROTTERDAM B.V.	869-22-230/2	Shaft Seal Complete	39294-1	39294	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Impeller - NULL	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Mechanical Seal - NULL	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Shaft - NULL	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Impeller Nut - M/E EXHAUST VALVE CAGES OVERHAUL	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Groove Ball Bearing - Dry Chemical Powder Fire Extinguishing System No.1	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Groove Ball Bearing - POWDER PLANTS	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Spacer Sleeve - (Critical spare part) Urgent Need Spare part A.S.A.P.	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Shaft Seal Ring - NULL	MD-50230- 41655	SDoC-50230- 41655	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5093	Circlip - NULL	MD-50230- 41655	SDoC-50230- 41655	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5088/2	SpacerSleeve -Pump type : CLH125-100-10G	MD-50263-41686	SDoC-50263-41686	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Groove Ball Bearing - NULL	2023/JAN/MD/026	2023/JAN/SD/015	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Spring Washer - NULL	2023/JAN/MD/027	2023/JAN/SD/015	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Shaft - NULL	2023/JAN/MD/028	2023/JAN/SD/015	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Key - Single suction.	2023/JAN/MD/029	2023/JAN/SD/016	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Mechanical Seal -	2023/JAN/MD/030	2023/JAN/SD/016	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Impeller Nut - Multi-stage.	2023/JAN/MD/031	2023/JAN/SD/016	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Circlip -	2023/JAN/MD/032	2023/JAN/SD/016	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Gland - Radially split.	2023/JAN/MD/033	2023/JAN/SD/017	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Split Ring -	2023/JAN/MD/034	2023/JAN/SD/017	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Stuffing Box Packing - Line shaft with inducer.	2023/JAN/MD/035	2023/JAN/SD/017	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Spacer Sleeve -	2023/JAN/MD/036	2023/JAN/SD/017	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Groove Ball Bearing - Weight: 1754 kg.	2023/JAN/MD/037	2023/JAN/SD/018	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Seal Ring - Single suction.	2023/JAN/MD/038	2023/JAN/SD/018	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086	Spring Ring -	2023/JAN/MD/039	2023/JAN/SD/018	NO
470	VIHMS000086	MARINE TECHNIC A/S	869-22-5086/2	Impeller - NULL	2023/JAN/MD/025	S2023/JAN/SD/015	NO
431	VIHMS000047	GEA WESTFALIA SEPARATOR DK A/S	869-22-194	Drive Belt - Standard No.029150701	2.15_MD_Spare_parts_2020-11	SDoC-GEA-WS-GROUP -04	NO
431	VIHMS000047	GEA WESTFALIA SEPARATOR DK A/S	869-22-194	Clutch Shoe, Compl. - Standard No.029150701	2.15_MD_Spare_parts_2020-11	SDoC-GEA-WS-GROUP -04	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
431	VIHMS000047	GEA WESTFALIA SEPARATOR DK A/S	869-22-194	Drive Belt - NULL	2.15_MD_Spare_parts_2020-11	SDoC-GEA-WS-GROUP-04	NO
431	VIHMS000047	GEA WESTFALIA SEPARATOR DK A/S	869-22-194	Solenoid Valve Block, Complete - NULL	2.15_MD_Spare_parts_2020-11	SDoC-GEA-WS-GROUP-04	NO
431	VIHMS000047	GEA WESTFALIA SEPARATOR DK A/S	869-22-194	Rubber-Metal Cushion - NULL	2.15_MD_Spare_parts_2020-11	SDoC-GEA-WS-GROUP-04	NO
391	VIHMS000007	ALFA LAVAL SINGAPORE PTE LTD	869-22-150	Gasket For Front Cover - NULL	000001	000001	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-168	Mechanical Seal - NULL	MD-50170-41595	SDoC-50170-41595	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-168	O-Ring Part No. Designation - NULL	MD-50170-41595	SDoC-50170-41595	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Impeller - Multi-stage.	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Shaft -	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Groove Ball Bearing - Radially split.	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Groove Ball Bearing -	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Mechanical Seal - Line shaft with inducer.	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Split Ring -	MD-50369-41791	SDoC-50369-41791	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5087	Circlip - Weight: 1754 kg.	MD-50369-41791	SDoC-50369-41791	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5088	Gasket - Model: air control	MD-50169-41594	SDoC-50169-41594	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5088	Mechanical Seal - Reduction ratio: 4.6804:1	MD-50169-41594	SDoC-50169-41594	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5088	Impeller - [38741960850 1]	o. Inter Sea Services Trading GmbH MD-50169-41594	o. Inter Sea Services Trading GmbH MD-50169-41594	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5088	Stub Shaft - Pump type : CLH125-100-10G	MD-50169-41594	SDoC-50169-41594	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Split Ring - NULL	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Impeller - NULL	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Mechanical Seal - NULL	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Circlip - NULL	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Spacer Sleeve - Marker: Ingresoll Rand	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Groove Ball Bearing - Type:NR-24-8	MD-50196-41621	SDoC-50196-41621	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5089	Groove Ball Bearing -Pilot Operated Regulatorwith integralpilot	MD-50196-41621	SDoC-50196-41621	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5090	Shaft - AUX. DIESEL GENERATOR AGGREGATE S, COMPLETE	MD-50168-41593	SDoC-50168-41593	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5090	Casing Cover - NULL	MD-50168-41593	SDoC-50168-41593	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5090	Bearing Bracket - NULL	MD-50168-41593	SDoC-50168-41593	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-5090	Mechanical Seal - NULL	MD-50168-41593	SDoC-50168-41593	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-69	Electrode Unit - 1 gasket set will be use to replenish spare on board.	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-69	Ignition Cable - Please ignore the quantities in the system for it was not updated actually.	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-69	Ignition Transformer -	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-69	Impeller - 1 dynamic seal will be used immediately and 1 for spare.	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-69	Thermocouple - Please ignore the quantities in the system for it was not updated actually.	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
437	VIHMS000053	HANIL-FUJI (KOREA)CO., LTD.	869-22-69	Timer220VAC 50/60Hz - Static sealwill be used immediately.	MD-869-22-69/HF-220585528	SDoC-869-22-69/HF-220585528	NO
399	414690	BURCKHARDT COMPRESSION AG	869-22-5091	Coupling Bolts With Guide, Complete - NULL	MD-34381	SDOC-34381	NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	869-22-165	Injection Nozzle, 12 IMO Number 1521 - Overhaul	MD-34073	SDOC-34073	NO
511	VIHMS000127	SPERRE AIR POWER AS	869-22-61	Valve Catcher, LP Delivery - Standard No.029150701	556122	SDoC-556122	NO
472	741836	MARINKEY PTE. LTD.	869-22-117	Clutch Shoe, Compl. - NULL	MK_01 2022	MK_11 2022	NO
472	741836	MARINKEY PTE. LTD.	869-22-117	Sight Glass - NULL	MK_01 2022	MK_11 2022	NO
472	741836	MARINKEY PTE. LTD.	869-22-117	Sight Glass - NULL	MK_01 2022	MK_11 2022	NO
472	741836	MARINKEY PTE. LTD.	869-22-117	Flowmeter - NULL	MK_01 2022	MK_11 2022	NO
472	741836	MARINKEY PTE. LTD.	869-22-117	Set Of Spare Parts	MK_02 2022	MK_11 2022	NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	869-22-115	Pressure Transmitter - PERSONAL PROTECTION GAS DETECTORS / RKI GX-2009A - NO 1			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	869-22-115	Pressure Transmitter - NULL			NO
468	VIHMS000084	MAN ENERGY SOLUTIONS, BRANCH OF MAN	869-22-22	Air Starter Complete - NULL	MD-32297	SDOC-32297	NO
459	VIHMS000075	KOREA MARINE SUPPLY CO., LTD	869-22-141	Filter - NULL	KMS-MD-869-22-141	KMS-SDoC869-22-141	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
459	VIHMS000075	KOREA MARINE SUPPLYCO., LTD	869-22-141	Carbon Filter For Drinking Water Fountain - Overhaul	KMS-MD-869-22-141	KMS-SDoC-869-22-141	NO
457	5468	KAESER KOMPRESSORER A/S	869-22-25/R/2	Separator - NULL	MD-31918	SDOC-31918	NO
457	5468	KAESER KOMPRESSORER A/S	869-22-25/R/R	Separator - Done by SRN Group	MD-31917	SDOC-31917	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-101	Electric/Pneumatic C - NULL	MD-49078-43733	SDoC-49078-43733	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-25	Separator - CONTR. PITCH PROPELLER PLANTS	MD-48309-42966	SDoC-48309-42966	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-17	Shaft - AUX. DIESEL GENERATOR AGGREGATE S, COMPLETE	MD-48145-42802	SDoC-48145-42802	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-17	Mechanical Seal -	MD-48145-42802	SDoC-48145-42802	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-17	Split Ring SIMSITE - Overhaul of AE#1 and #3. AUX. DIESEL GENERATOR AGGREGATE S, COMPLETE	MD-48145-42802	SDoC-48145-42802	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-17	V-Ring - Auxiliary Engine No. 1	MD-48145-42802	SDoC-48145-42802	NO
447	VIHMS000063	INTER SEA SERVICES AND TRADING GMBH	869-22-17	Impeller SIMSITE - Auxiliary Engine No. 2	MD-48145-42802	SDoC-48145-42802	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-144	Window Wiper Blade - NULL	MD-869-22-144/HF-220936090	SDoC-869-22-144/HF-220936090	NO
437	VIHMS000053	HANIL-FUJI (KOREA) CO., LTD.	869-22-144	Spring - NULL	MD-869-22-144/HF-220936090	SDoC-869-22-144/HF-220936090	NO

Supplier ID	SupplierCode	Supplier Name	P.O. No	Item description	MD No	SDoC No	HAZARDOUS MATERIALS DETECTED?
565	VIHMS000145	VIKING LIFE-SAVING EQUIPMENT A/S	869-22-247	Hydraulic Hose 1/2 in.-A	MD-56099	Multi-SDoC-333680	NO
565	VIHMS000145	VIKING LIFE-SAVING EQUIPMENT A/S	869-22-247	Hydraulic Hose 1/2 in.-B	MD-56100	Multi-SDoC-333680	NO

